

Date: Monday, 1/8/2007 11:08:43 AM
 User: Kim Johnston

Process Sheet

Customer : CU-DAR001 Dart Helicopters Services Drawing Name : BUSHING
 Job Number : 30198
 Estimate Number : 10175
 P.O. Number : *N/A*
 This Issue : 1/8/2007 S.O. No. : *N/A*
 Prsht Rev. : NC Part Number : D2570
 First Issue : *N/A* Type : MACHINED PARTS Drawing Number : D2570 REV A
 Previous Run : 29776 Project Number : N/A
 Material : *N/A*
 Due Date : 1/20/2007 Qty: 500 Um: Each
 Written By : *[Signature]*
 Checked & Approved By : *[Signature]*
 Comment : Est E 0206.29 Re-format; Removed finishing; Material change K
 J

Additional Product

Job Number:



Seq. #: Machine Or Operation: Description :

1.0 M303R0750 303 Round Bar .75"



Comment: Qty.: 0.0810 f(s)/Unit Total: 40.4775 f(s) *Scrap 2 parts 10" no good M103503*
 Material: Ø0.750 AISI 303 SS Rod (M303R0.750) *Scrap 3 parts of 10" no good M102318*
 Batch *M103503 458/ M102318 x 11.62* *J.F 07/02/22*

2.0 HARDINGE HARDINGE CNC LATHE SMALL



Comment: HARDINGE CNC LATHE SMALL
 Machine as per folio FA198
 Deburr and tumble

J.F 07/02/22

3.0 QC2 INSPECT PARTS AS THEY COME OFF MACHINE



Comment: INSPECT PARTS AS THEY COME OFF MACHINE

J.F 07/02/22

4.0 QC8 SECOND CHECK



Comment: SECOND CHECK

J.F 07-03-02

5.0 PACKAGING 1 PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1
 Identify and Stock
 Location: *0*

Ce 7/3/05 (506)

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes ☒ No ☐ DQA: TS Date: 07/03/05
 QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Monday, 1/8/2007 11:08:43 AM
User: Kim Johnston

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: BUSHING

Job Number: 30198

Part Number: D2570

Job Number:



Seq. #:

Machine Or Operation:

Description :

6.0

QC21

FINAL INSPECTION/W/O RELEASE



506

Comment: FINAL INSPECTION/W/O RELEASE

2507103/05

Job Completion



U 07-0305

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____


QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries



RELEASED
76/09/18 DS



BREAK ALL SHARP CORNERS 0.010 MAX
MATERIAL: AISI 303 — 0.75 DIA STOCK

SHOP COPY
RETURN TO
ENGINEERING
UNCONTROLLED COPY
SUBJECT TO AMENDMENT
WITHOUT NOTICE
WORK ORDER
NO. 30198